



# Monthly Recall Report November, 2012

Division

Veh. Type

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V532"/>	<input type="text" value="AIRSTREAM, INC."/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2006 - 2009 CLASSIC"/>
Subject:	Population:	Influenced By:		
<input type="text" value="The Hydraulic Brake Hose may Fail due to Flexing"/>	<input type="text" value="715"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V532&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V532&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V534"/>	<input type="text" value="Mitsubishi Fuso Truck of America, I"/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2012 - 2013 FEC52"/> <input type="text" value="2012 - 2013 FEC72"/> <input type="text" value="2012 - 2013 FEC92"/> <input type="text" value="2012 - 2013 FGB72"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Parking Brake Lock Nut may be Loose"/>	<input type="text" value="6538"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V534&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V534&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V538"/>	<input type="text" value="BLUE BIRD BODY COMPANY"/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2013 - 2014 VISION"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Brake Light Switch may Keep Brake Lights on"/>	<input type="text" value="452"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V538&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V538&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V539"/>	<input type="text" value="Prevost Cars, Inc."/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2009 - 2013 9700"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Wheelchair Lift Safety Pins Missing or Unusable"/>	<input type="text" value="44"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V539&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V539&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V543"/>	<input type="text" value="FOREST RIVER, INC."/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2011 - 2012 LIGHTNING"/> <input type="text" value="2011 - 2012 LOW RIDER"/> <input type="text" value="2011 - 2012 OUTLAW"/> <input type="text" value="2011 - 2012 RANGER"/> <input type="text" value="2011 - 2012 V-LOW"/> <input type="text" value="2011 - 2012 WORK N TOW"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Improperly Machined Wheels"/>	<input type="text" value="2200"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V543&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V543&searchtype=quicksearch&summary=true)



# Monthly Recall Report November, 2012

Division

Veh. Type

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V544"/>	<input type="text" value="Tems Global Sanayi Ve Ticaret A.S."/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2007 - 2010 TS35"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Insufficient Number of Emergency Exits\FMVSS 217"/>	<input type="text" value="71"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V544&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V544&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V545"/>	<input type="text" value="Mitsubishi Fuso Truck of America, I"/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2005 - 2007 FE83D"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Fuel Pipes May Crack"/>	<input type="text" value="13644"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V545&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V545&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V546"/>	<input type="text" value="Navistar, Inc."/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2013 - 2013 9900"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Front Brake S-Cams may Fracture"/>	<input type="text" value="6779"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V546&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V546&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V547"/>	<input type="text" value="SETRA OF NORTH AMERICA"/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2012 - 2013 S407 CC"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Alternator Ground Wire Short Circuit"/>	<input type="text" value="203"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V547&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V547&searchtype=quicksearch&summary=true)

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
<input type="text" value="12V549"/>	<input type="text" value="Nova Bus"/>	<input type="text"/>	<input type="text"/>	<input type="text" value="2010 - 2010 NOVA LFS"/>
Subject:	Population:	Influenced By:		
<input type="text" value="Window Handles may Break"/>	<input type="text" value="26"/>	<input type="text" value="MFR"/>		

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V549&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V549&searchtype=quicksearch&summary=true)



# Monthly Recall Report November, 2012

Division  [Key Word](#)  
 Veh. Type

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="12V552"/>	<input type="text" value="Daimler Trucks North America"/>	<input type="text"/>	<input type="text"/>	2010 - 2013 CUSTOM CHASSIS XB
<b>Subject:</b>		<b>Population:</b>	<b>Influenced By:</b>	2010 - 2013 CUSTOM CHASSIS XC
<input type="text" value="Brake Lights &amp; Cruise Control Issues"/>		<input type="text" value="7594"/>	<input type="text" value="MFR"/>	

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V552&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V552&searchtype=quicksearch&summary=true)

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="12V554"/>	<input type="text" value="Medtec Ambulance Corporation"/>	<input type="text"/>	<input type="text" value="PE11-041"/>	2009 - 2011 AMBULANCE
<b>Subject:</b>		<b>Population:</b>	<b>Influenced By:</b>	
<input type="text" value="Bench Seat Top may Collapse"/>		<input type="text" value="996"/>	<input type="text" value="ODI"/>	

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V554&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V554&searchtype=quicksearch&summary=true)

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="12V559"/>	<input type="text" value="WINNEBAGO INDUSTRIES INC."/>	<input type="text"/>	<input type="text"/>	2009 - 2013 ERA
<b>Subject:</b>		<b>Population:</b>	<b>Influenced By:</b>	2010 - 2013 NAVION
<input type="text" value="Incorrect Fuses Installed which may Result in Fire"/>		<input type="text" value="2944"/>	<input type="text" value="MFR"/>	2010 - 2013 REYO
				2009 - 2013 VIA
				2009 - 2013 VIEW

To see a summary of the recall click the Link below.  
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\\_id=12V559&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V559&searchtype=quicksearch&summary=true)